

10 Tips



for making sure your contractor measures up.

1. Hire only licensed contractors.
2. Check contractor's license at www.dpor.state.va.us or (804) 367-8511.
3. Get three references, review past work.
4. Get at least three bids.
5. Get a written contract and don't sign anything until you completely understand the terms.
6. Pay 10% down, or \$1,000, whichever is less.
7. Don't let payments get ahead of work. Keep record of payments.
8. Don't make final payment until you're satisfied with the job.
9. Don't pay cash.
10. Keep a job file of all papers relating to your project.

www.dpor.state.va.us
(804) 367-8511

